



03500.017413

PATENT

c of c
\$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
SHUJI YAMADA ET AL.) Examiner: Chrisopher G. Yound
Appln. No.: 10/619,575) Art Unit: 1756
Filed: July 16, 2003)
For: METHOD OF MANUFACTURING)
MEMBER PATTERN, METHOD OF)
MANUFACTURING WIRING)
STRUCTURE, METHOD OF)
MANUFACTURING ELECTRON)
SOURCE, AND METHOD OF)
MANUFACTURING IMAGE)
DISPLAY DEVICE)
U.S. Patent No.: 7,067,236 B2)
Issued: June 27, 2006) December 21, 2006

Certificate
DEC 28 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank A. Delucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
603501v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 15, "pattern" should read --pattern,--

COLUMN 4

Line 66, "to extent" should read --to extend--

COLUMN 9

Line 20, "photosensitive" should read --photosensitive insulating material--

Line 24, "after pat-" should read --after being pat--

Line 27, "percents" should read --percent--

Line 32, "after dried." should read --after being dried.--

Line 55, "after dried," should read --after being dried,--

Line 56, "percents" should read --percent--

COLUMN 10

Line 5, "after baked" should read --after being baked--

Line 5, "before baked" should read --before being baked--

Line 42, "are formed." should read --is formed.--

Line 53, "for maintain" should read --for maintaining--

Line 58, "is formed" should read --and is formed--

COLUMN 12

Line 45, "11B particularly" should read --11B. Particularly--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 63, "spacer," should read --a spacer,--

COLUMN 15

Line 14, "among from" should read --from among--

Line 17, "dried" should read --being dried--

Line 60, "dried" should read --being dried--

COLUMN 17

Line 18, "percents" should read --percent--

Line 23, "ink jet applying." should read --applying ink jet--

Line 31, "Whereby," should read --Thereby,--

Line 36, "percents" should read --percent--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18

Line 45, "voltages," should read --voltage,--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

603501v1



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 15, "pattern" should read --pattern,--

COLUMN 4

Line 66, "to extent" should read --to extend--

COLUMN 9

Line 20, "photosensitive" should read --photosensitive insulating material--

Line 24, "after pat-" should read --after being pat--

Line 27, "percents" should read --percent--

Line 32, "after dried." should read --after being dried.--

Line 55, "after dried," should read --after being dried,--

Line 56, "percents" should read --percent--

COLUMN 10

Line 5, "after baked" should read --after being baked--

Line 5, "before baked" should read --before being baked--

Line 42, "are formed." should read --is formed.--

Line 53, "for maintain" should read --for maintaining--

Line 58, "is formed" should read --and is formed--

COLUMN 12

Line 45, "11B particularly" should read --11B. Particularly--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 63, "spacer," should read --a spacer,--

COLUMN 15

Line 14, "among from" should read --from among--

Line 17, "dried" should read --being dried--

Line 60, "dried" should read --being dried--

COLUMN 17

Line 18, "percents" should read --percent--

Line 23, "ink jet applying." should read --applying ink jet--

Line 31, "Whereby," should read --Thereby,--

Line 36, "percents" should read --percent--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,067,236 B2

DATED : June 27, 2006

INVENTOR(S) : SHUJI YAMADA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18

Line 45, "voltages," should read --voltage,--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,067,236 B2

No. of add'l. copies
@ 30¢ per page

